


HP-B SERIES HEAT PUMP REPLACEMENT PARTS

Parts of HP-A Models: HP5.6B / HP7.8B / HP9.5B / HP14B1

[Back to Table of Content](#)



Ver: 210315

KEY NO.	POOLSPA CODES	PART NO.	DESCRIPTIONS	PIECE (S) REQUIRED	RETAIL PRICE 2025
1	21720510005	87990226	Compressor HICHLY CG633GB1-C for HP5.6B	1	47,000.00
1	21720510010	87990218	Compressor HICHLY CHX33SC4-U for HP7.8B	1	50,000.00
1	21720510015	87990211	Compressor HICHLY CHV33YC6-U for HP9.5B	1	65,000.00
1	21720510020	87990247	Compressor Sanyo C-SBN261H5A for HP14B1	1	141,000.00
2	21720510025	87990227	Heat Exchanger (HP5.6B)	1	39,000.00
2	21720510030	87990219	Heat Exchanger (HP7.8B)	1	44,000.00
2	21720510035	87990212	Heat Exchanger (HP9.5B)	1	52,000.00
2	21720510040	87990248	Heat Exchanger (HP14B1)	1	74,000.00
3	21720510045	87990272	Wire Cover	1	500.00
4	21720510050	87990269	Water Connection	2	1,700.00
5	21720510055	87990258	Pressure Gauge (FOR COMPRESSOR)	1	3,000.00
7	21720510060	87990271	High Pressure Switch	1	1,500.00
7	21720510065	87990273	Low Pressure Switch	1	1,500.00
14	21720510070	87990225	Compressor Capacitor 35UF , 5.6B	1	3,000.00
14	21720510075	87990217	Compressor Capacitor 50UF , 7.8B	1	3,000.00
14	21720510080	87990210	Compressor Capacitor 55UF , 9.5B	1	4,000.00
14	21720510085	87990246	Compressor Capacitor 60UF , 14B	1	4,000.00
15	21720510090	87990265	Controller Panel (PCB Board)	1	12,000.00
15	21720510335	114215897	LCD Controller Panel	1	9,000.00
15	21720510340	3158500001	Plastic Case for LCD Controller Panel	1	3,000.00
15	21720510345	114266192	Mechanical switch (For Series B2)	1	4,000.00
9	21720510095	87990232	Controller for HP5.6B / HP7.8B / HP9.5B	1	18,000.00
16	21720510100	87990251	CHILLER 300 for HP5.6 , 7.8 , 9.5 , 14B1	1	22,000.00
17	21720510105	87990229	Fan motor Capacitor 10000-DK29 2UF(HP5.6-7.8B)	1	800.00

17	21720510110	87990214	Fan motor Capacitor 10000-DK28 3UF(HP9.5B)	1	900.00
17	21720510115	87990252	Fan motor Capacitor 10000-DK26 4UF(HP14B1)	1	900.00
19	21720510120	87990230	Fan Leave (HP5.6B)	1	1,800.00
19	21720510125	87990221	Fan Leave (HP7.8B)	1	1,800.00
19	21720510130	87990215	Fan Leave (HP9.5B)	1	2,000.00
19	21720510135	87990253	Fan Leave (HP14B1)	1	3,000.00
20	21720510140	87990231	Fan Motor (HP5.6B)	1	7,000.00
20	21720510145	87990222	Fan Motor (HP7.8B)	1	7,000.00
20	21720510150	87990216	Fan Motor (HP9.5B)	1	9,000.00
20	21720510155	87990254	Fan Motor (HP14B1)	1	12,000.00
23	21720510160	87990228	4-Way Valve (HP5.6B)	1	5,000.00
23	21720510165	87990220	4-Way Valve (HP7.8B)	1	6,000.00
23	21720510170	87990213	4-Way Valve (HP9.5B)	1	6,000.00
23	21720510175	87990249	4-Way Valve (HP14B1)	1	11,000.00
24	21720510180	87990268	Water Flow Switch	1	5,000.00
25	21720510185	87990266	Temperature Sensor (Copper)	3	1,200.00
25	21720510190	87990267	Temperature Sensor (Plastic)	1	1,200.00
26	21720510195	87990250	Running Capacitor for HP14B1	1	5,000.00
27	21720510200	87990255	AC Contactor HCC-1NU04AA for HP14B1	1	4,000.00
28	21720510350	114276819	Fan Mesh (Please specify the Barcode)	1	5,000.00

***** Key No. 6 , 8 , 9 , 10 , 11 , 12 , 13 , 18 , 21 , 22 are not available