


2.0" CLAMP TYPE MULTIPORT VALVE REPLACEMENT PARTS

Parts of 2.0" CLAMP TYPE MULTIPORT VALVE Models: MPV-08

[Back to Table of Content](#)



KEY NO.	POOLSPA CODES	PART NO.	DESCRIPTIONS	PIECE (S) REQUIRED	RETAIL PRICE 2025
1	20650510025	01013003	Handle (Big)	1	280.00
1	20650510030	01013002	Handle (Small)	1	280.00
1	20650510035	01013001	Handle (Meshy)	1	280.00
2	20650510040	03018008	Pin for Handle	1	150.00
3	20650510185	01181027	Washer for Handle	1	80.00
4	20650510615	01181028	Defend Lock	1	80.00
5	20650510620	01020009	2.0" Lid	1	1,710.00
6	20650510085	01181002	Washer for Spring	1	80.00
7	20650510095	02011022	O-Ring for Valve Rotor	2	150.00
8	20650510215	03014014	Spring for Valve	1	1,430.00
9	20650510625	89280805	2.0" Valve Rotor with Spider Gasket	1	1,050.00
10	20650510630	02010003	O-Ring for Lid	1	150.00
11	20320511410	E190213	2.0" Body with Diffuser	1	3,900.00
12	20320511305	E190109	Connector for Pressure Gauge/Stopper	1	80.00
13	20650510180	89021307	Drain Plug With O-Ring	1	150.00
14	20320511020	06011029	Maximum 40PSI Indication, Stainless Steel Casing	1	990.00
14	20320510005	06021013	Plastic Pressure Gauge with O-ring	1	420.00
15	20320510200	02020016	O-Ring for Connector	6	100.00
15	20320510201	111202472	O-Ring for Connector - Year2022	6	150.00
16	20650510260	430300989	2.0" Union (Imperial/Metric)	3	280.00
16	20650510265	01051033	2.0" Connector (White)	3	280.00
17	20650510270-1	430300989	2.0" Union (Imperial/Metric)	3	280.00
18	20650510275	430170991	2.0" Union Nut (Black)	3	280.00
18	20650510280	01051032	2.0" Union Nut (White)	3	280.00
19	20320510245	89280104	Sight Glass with O-Ring	1	150.00
20	20650510255	02011005	O-Ring for Diffuser	1	80.00
21	20320511415	919301023	MPV08 Upper Part	1	4,100.00

Note: item 21 include item 1-10